ENGINEERING CHANGE NOTICE
DART AEROSPACE LTD

Date:	10.12.01	Job No.:	P2010034	ADR Yes/No:	NO	ADR Date:		ECN #:	10- 658
Product No.:	D212-580			Created By:	KB	Approved By:			
Product Name:	Dual Cargo Mirror and LED Pulse Light Kit			Checked By:	DS	General Manager Approval:	NA		

Distribution	Reqd	Resp	Initial / Date	Distribution	Reqd	Resp	Initial / Date
Production Manager / Coord.	Y	LL	JNF 10-12-14	DQA / QA Coord.	N		
Purchasing Coord.	Y	CL	CX 10/12/14	QC Coordinator	N		
Production Engineering Coord.	Y	DD/EC	E 10.12.23	Customer Technical Support	Y	MB	b 10.12.14
				Marketing	Y	SW	SW 10.12.14
				Customer Order Processing	N		

Reason for Change:
Relese DSI 9538 to correct typo on part number.

Documents Affected:
MDL-D212-580 Rev. G
DSI 9538 Rev. A

PARTS MUST COMPLY [X]   PREVIOUS PARTS SATISFACTORY [ ]

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Master Document List (MDL)	Y	KB	MDL-D212-580 Rev. G	10.12.01
6	Update Product Compatibility Matrix	N			
7	Create Eurocopter Form (FEE)	N			
8	Notify TC / FAA of Change	N			
9					

#	Document Control Actions	Reqd	Resp	Notes	Complete
10	Move Electronic Files	Y	KJ		10.12.14
11	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ	Add DSI 9538 Rev. A	10.12.14
12	Update Approved/Preliminary PDF Files	Y	KJ		10.12.14
13	Update Document Record (DR)	N		DR combined into MDL	
14	Update Product Development Summary	N			
15	Update QSI 021 and/or STC Approval List	N			
16	Update Parts / STC Database	Y	KJ	Add 205838-1	10.12.14
17	Update / Verify ARC Database	N			
18	Create / Update Change Record Form / Item Card Database	N			
19	Create / Update PPP's	N			
20	Update Document Control Database / Laminated Dwgs	N			
21	Update Grey Project / Electronic Binder PDF Files	Y	KJ		10.12.14
22	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		10.12.14
23					
24					

Description / Action:

Update BOM/Routing for D212-580-043 to replace 206838-1 with 205838-1 per DSI 9538.
Ensure all D212-580-043 kits in stock are updated.
Purchase 205838-1 as required.

ECN Verified & Complete: _____   Date: 11/2/4